
Dart Aerospace Ltd. Date Monday, 22/10/2007 2:17:15 PM User Linda Lacelle **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : ARM Job Number : 35296 - 2 **Estimate Number** : 12882 P.O. Number Part Number : D3560042 This Issue : 22/10/2007 S.O. No. : **Drawing Number** D3560 UNDE Prsht Rev. : NC Project Number : N/A First Issue : 11 Type : SMALL /MED FAB **Drawing Revision** : C Previous Run : 35030 Material Written By Due Date : 29/10/2007 Qty: 14 Um: Each Checked & Approved By Comment : Est Rev:A New Issue 07.05.24 EC est rev B **ECN 987** 07.10.09 EC verified by: DD Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1.0 M6061T6B0500X05000 6061-T6 Bar .50" x 5.0" Comment: Qty.: 1.4648 f(s)/Unit Total: 20.5065 f(s) 6061-T6 Bar 0.50" x 5.00" Batch: M106/8.2 02/11/36 2.0 BAND SAW BAND SAW Comment: BAND SAW Cut blanks 16.750" long 3.0 HAAS1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA694 Rev: 4 & Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 4.0 QC2 INSPECT PARTS AS THEY COME OFF MACHINE Comment: INSPECT PARTS AS THEY COME OFF MACHINE 5.0 QC8 SECOND CHECK


Page 1

Comment: SECOND CHECK


Form: rprocess



Date: . Monday, 22/10/2007 2:17:15 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35296 Part Number: D3560042 Job Number: Seq. #: Machine Or Operation: Description: 6.0 D35921 PLATE Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) PLATE .02.04 7.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE ABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 STEP: 1- clean material (buff bracket and bottom of arm with blue pad 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (60) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) 8.0 QC5 INSPECT WORK TO CURRENT STEP Comment: INSPECT WORK TO CURRENT STEP X5045 9.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 10.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 8:02.05 Chemical Conversion Coat as per QSI 005 4.1



Date: . Monday, 22/10/2007 2:17:15 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35296 Part Number: D3560042 Job Number: Seq. #: Machine Or Operation: Description: 11.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 7.02.05 12.0 D2808 Spacer Comment: Qty.: 1.0000 Each(s)/Unit Total: 14.0000 Each(s) 35330 Spacer 13.0 SMALL FAB 1 SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 INSPECT WORK 1 Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING 1 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: CVH 16.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion



D3560-1 ARM (-041, SHOWN) OR D3560-2 ARM (-042, OPPOSITE) D3592-1 PLATE. SEE DETAIL A .


> D3560-041 ARM WELDMENT (SHOWN). D3560-042 ARM WELDMENT (OPPOSITE)


03560-3 ARM (-043, SHOWN) OR D3560-4 ARM (-044, OPPOSITE) D3592-1 PLATE, SEE DETAIL A

D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)

> GENERAL NOTES 1) WELD PER QSI 004

> > 07.06.19





DETAIL A (SCALE 1:1) 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED 4) ALL DIMENSIONS ARE IN INCHES

RELEASED

UNDER REVIEW

SCALE

07.10.22 DE


C 07.06.19 REMOVE POWDER COAT В 07.01.15 REDESIGN AS WELDMENT, ADD POCKETS A 06.09.25 NEW ISSUE DART AEROSPACE LTD. 9 DART CHECKED 03560 SHEET & OF 3 DATE TITLE


ARM WELDMENT


2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1


COPYRIGHT @ 2006 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.











DART AEROSPACE LTD	Work Order:	55246		
Description: Arm	Part Number:	D3560-2		
Inspection Dwg: D3560 Rev: B		Page 1 of 1		

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	5063				
Ø0.196	+0.005/-0.001	196	/			
Ø1.000	+0.010/-0.001	1,003	/			
0.500	+/-0.010	.499	V			
0.250	+/-0.010	.252	V			
0.275	+/-0.010	,277	V			
0.188	+/-0.010	197	/			
2.000	+/-0.010	2.003	/			
1.700	+/-0.010	1.703	/			
Ø0.385 x 100°	+/-0.010 x 0.5°	3841/08	/			
0.250 Deep	+/-0.010	.251				
			74			
1-1-11-1						

Measured by:	Audited by:	ゴト	Prototype Approval:	N/A
Date: 2/12/06	Date:	07/12/06	Date:	N/A

R	ev	Date	Change	Revised by	Approved
1	A	07.01.17	New Issue	KJ/JLM	
-	В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM	

Dart Aerospace Ltd

W/O:) WORK ORDER CHANGES							1
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng./ Prod Mgr	Approval QC Inspector
			-			1	
			7/				
Part No		PAR #: Fault Category:	NCR. Yes	No DO	۸.	Date:	

QA: N/C Closed: ____ Date: ___

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
Page 1	DATE STED Description of NC			Corrective Action Section B	Verification	A		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
		- 1 H	4					
					D .			
			#					
						Na.		

NOTE: Date & initial all entries